*** *** *	△ * 1	TT	E 40 E0
Work	Order	TD.	54353



Page 1

December 8, 2009 9:51:03 AM

Item ID:

D412-724-041

Accept



Setup Start



Revision ID:

Item Name:

Required Date: 15/12/2009

Head Rest Assembly, Center

Start Date:

08/12/2009

Start Qty: 20.00

reeq'd Qty: 20.00



Cust Item ID:

Customer:

Reference:

Tooling:

Date:

Run

Start

Stop

Stop

Approvals:

QC:

Revision Nbr

Rev N/A

Date:

SPC (Y/N):

Date:

Accept

Reject Reject Insp.

Sequence ID/ Work Center ID Draw Nbr

Operation Description Set Up/ **Run Hours**

Draw Number

Draw Rev.

Plan Code

Qty

Qty

Number Stamp

N/A 100

DOCUMENT CONTROL

Memo

0.00

0.00

Document Control

Memo
If D412-724-041 is a W/O on it's own, □Photocopy bluefile and create labels per
DDD D412-724-041 CHG001

cable only

110

Pick Kit

0.00

Packaging

Packaging

Memo

0.00

10-1-07

120

QC4-100% Inspect kits for completeness

0.00

3) Siobilz 5

Lourte

Quality Control

Memo

0.00

Dart Ae	rospace l	_td						•
W/O:			WO	RK ORDER CHANG	ES		•	>
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
11:0						.,		
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQA:	Date: _	
	Res	solution:	Disposition);	_ QA: N/C CI	losed:	Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	₹)		*
		Description of NC		Corrective Action Section	on B	Verification	Annuoval	A
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Approval Chief Eng	Approval QC Inspector
			1					

		Description of NC	Description of NC Corrective Action Section B				A	A
DATE	STEP	Section A	Initial Action Description Sign & Chief Eng Chief Eng Date			Verification Section C	Approval Chief Eng	Approval QC Inspector
	:							
							:	
,								
					3			
					-			
								1

NOTE: Date & initial all entries

Work Order ID 54353



Page 2

December 8, 2009 9:51:04 AM

Required Date: 15/12/2009

Item ID: **Revision ID:** D412-724-041

Accept



Setup Start



Start Date:

Item Name:

08/12/2009

Start Qty: 20.00

Req'd Qty: 20.00



Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Process Plan: _____ Date: ____

Head Rest Assembly, Center

Tooling:

SPC (Y/N):

Date:

Draw

Rev.

Plan

Code

Date:

Reject

Qty

Run

Accept

Qty



Insp.

Stop

Start

Stop

Sequence ID/

Work Center ID

130

Packaging

Packaging

Operation Description Set Up/ **Run Hours**

0.00

Packaging

Memo

QC: Date:

0.00

Identify and pack for shipping as per PPP D412-724

Memo

Number Stamp

Reject

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

10/01/2595)

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			WC	ORK ORDER CHANG	iES	,		<u>e</u> :	*
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
¥7, 1									
•									
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA	۸:	Date:	
i	R	esolution:	Dispositio	n:	_ QA: N/C CI	osed:	·	Date:	-
NCR:		V	VORK ORD	ER NON-CONFORM	ANCE (NCF	R)			
DATE	STEP	Description of NC			ion B	Verific	ation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	k Section		Chief Eng	QC Inspector
						-			
								·	

NOTE: Date & initial all entries

Picklist Print Page 1 December 8, 2009 9:51:08 AM Work Order ID: 54353 Parent Item: D412-724-041 Parent Item Name: Head Rest Assembly, Center Start Date: 08/12/2009 **Required Date: 15/12/2009** Start Qty: 20.00 Required Qty: 20.00 Comments: Replacement Mfg/ Bin Primary Unit of Component Item ID/ Last Route Qty on Remaining **Qty** Date Status Item Location Location Seq ID Measure Hand Qty To Pick Issued Item Name Issued Item ID Purch AN525-10R6 . ~ Each 110.0000 80.0000 No 120 Purchased M113595 10-1-22 Screw 5,10 Warehouse Loc Qty Loc Code Location Main Warehouse ST 110 101203 110 120 D3303-041 Each 3.0000 20.0000 Manufactured No Loc Qty Loc Code Warehouse Location Main Warehouse ST 3 44448 3 Manufactured 120 Each 4.0000 20.0000 Tube Assembly Loc Qty Warehouse Loc Code 500 Location Main Warehouse

Dart Ae	rospace L	td				1 _{4.4}			f
W/O:			WO	RK ORDER CHANGE	S			*	
DATE	STEP	PRO	OCEDURE CHAN	NGE	By Date Qty			Approval Chief Eng / Prod Mgr	Approva QC Inspector
								,	
						- N to 644-			
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	A :	_ Date: _	
	Res	olution:	Disposition	n:	QA: N/C C	losed:		Date: _	
NCR:			WORK ORDE	ER NON-CONFORMAN	ICE (NCI	₹)			
DATE	STEP	Description of NC			Section B		cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	🗴 Secti		Chief Eng	QC Inspector
-		and the same of th							
								·	

NOTE: Date & initial all entries

3.0 INSTALLATION PROCEDURE

To install a Dart Head Rest Assembly:

- 3.1 If installed, remove the existing Head Rest Assembly by pulling the quick release pin that attaches it to the seat. Make note of the installation position (if applicable).
- 3.2 Inspect the seat for damage in the vicinity of the Head Rest Assembly. Consult the Aircraft Maintenance Manual for disposition if damage is observed.
- 3.3 If only replacing the Head Rest with the equivalent Dart D3303-041 Head Rest, separate the existing Head Rest from the existing Tube Assembly by undoing 4 screws. Re-assemble D3303-041 Head Rest with existing Tube Assembly by installing 4 screws and tightening to 15-25 in lb.
- 3.4 If only replacing the Tube Assembly with a Dart D3304-041/-043/-044 Tube Assembly, separate the existing Head Rest from the existing Tube Assembly by undoing 4 screws. Re-assemble existing Head Rest with Dart D3304-041/-043/-044 Tube Assembly by installing 4 screws and tightening to 15-25 in lb.
- 3.5 Slide the new or modified Head Rest Assembly into the seat tube and lock in place at the same location that the old Head Rest Assembly was installed (if applicable) using the quick release pin. Ensure pin is properly engaged.

4.0 WEIGHT AND BALANCE

There is negligible weight change associated with the installation of the Dart Head Rests.

5.0 PARTS LIST

QTY -011	QTY -041	QTY ′-043	QTY -044	Part Number	Description
X				D412-724-011	Dart Replacement Head Rest Kit, for 205/212/412
2	Х			D412-724-041	Head Rest Assembly, Center
1		Х		D412-724-043	Head Rest Assembly, LH
1			Х	D412-724-044	Head Rest Assembly, RH
	1 ,	1	1	D3303-041 <	Head Rest
	1			D3304-041	Tube Assembly
		1		D3304-043	Tube Assembly
			1	D3304-044	Tube Assembly
	4	4	4	AN525-10R6	Screw
	4	4	4	AN525-	10R6